



## Updating of FBs OS V4.65

08/18/2010

- Support RTC chips : HT1381/ISL1208/S35390A
  - D4053=0, Without RTC chip
  - D4053=1, RTC chip is HT1381
  - D4053=2, RTC chip is ISL1208
  - D4053=3, RTC chip is S35390A
- Improve the efficiency of reading RTC chip ISL1208